





BEST AVAILABLE COPY






2ND FLOOR PLAN

FIG. 2

unchanged



3RD FLOOR PLAN

FIG. 3

unchanged.




Fig. 4




Fig. 5





Fig. 6

Substructure




Interface Level

first tunnel walls
second tunnel walls
and having a third
length

an interface level comprising a plurality of
adjacent, poured-in-place concrete


fourth tunnel walls
vertically aligned with
said second tunnel
walls and having a
fourth length



2ND FLOOR PLAN

Superstructure


superstructure comprising a plurality of parallel adjacent, spaced in-place tunnels having [hatched pattern] that are each vertically aligned with one of said first and second tunnel walls.



3RD FLOOR PLAN

FIG. 3

Color-coded
Schematic
Corresponding to
Figures 5 and 6



**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☒ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.